

Technical Data Sheet

Re-waxing treatment for “Barbour” type garments

- Makes the garment new, gives it the original appearance as just treated

Method of use: Melt the product between 70 – 90 °C to make it perfectly liquid and distribute it evenly with a brush. Then hang the garment, leaving it cool well and leave it rest for at least 2 hours.

Warning: This product is dangerous, during heating use an effective ventilation (also a forced ventilation if necessary) and protect the user with a mask with a suitable filter for this kind of product.